

Rep → news

2022-11-21 | # 008



Content

- Elimination MPA 4111 V1.1
- Modification marking VPS 50x ...

Rep → news

2022-11-21 | # 008

Elimination

MPA 4111 V1.1

Due to the currently still problematic delivery situation for certain components, the MPA 4111 V1.1 will be discontinued prematurely.

The currently expected delivery times for this special version are unfortunately not justifiable and cannot be communicated to the customers.

The version MPA 4111 V1.1 can technically be replaced by the version MPA 4112 V1.1.

The parameter setting is identical for both versions.

Attention: Observe installation dimensions.

Valid with immediate effect from the date of distribution of this RepNews.

Please inform your customers!

Elimination // MPA 4111 V1.1 Timetable		Deadline Valid from		
Announcement Elimination RepNews 08-2022		2022-11-21		
Last order		no		
Designation		Order No.	Replacement	Order No.
MPA 4111 V1.1 / 230 VAC		259058	MPA 4112 V1.1 / 230 VAC	259066
MPA 4111 V1.1 / 115 VAC		259062	MPA 4112 V1.1 / 115 VAC	259070

Rep → news




2022-11-21 | # 008

Modification

Marking VPS 50x

Due to the addition of the UKCA marking and to improve the production process, the VPS type plate is modified and additional markings are applied.

1. The barcode on the type plate is removed. For clear identification of the VPS 50x, a label with datamatrix code, the order number and the serial number is applied to the aluminium bottom part (picture 1).
2. A label with data matrix code is applied to the opposite side of the aluminium bottom part. This is only used for internal production logistics and does not provide any information about the order or serial number of the VPS (picture 2).
3. The production date is now visible on the type plate (production date/warranty/invoice date: Please refer to RepNews 05/2020). The round date sticker is omitted (picture 3).



Production date
22 = 2022
11 = November

Please inform your customers!